

Painting Classroom Tools and Materials

The following is a list of tools/materials that you are **required** to bring to your Painting Class:

- Tool Belt – required to keep your lab and work area in safe and clean order (optional, but suggested)
- Lace-Up or Pull-On Work Boots – work boots are not required to be steel toed for our training facility however they must be made of sturdy leather
- Clear, Non-Tinted Safety Glasses with no reflective coating – you must be able to see your eyes through the lens (yellow and light blue lenses are OK as long as they do not have a reflective coating). All safety glasses must meet ANSI Z87.1-2003 standards and must be Z87+ rated. Prescription eyewear is allowed if it meets ANSI Z87-2 standards, otherwise, “over-the-glass” safety eyewear is required.
- Respirator and Cartridges: All painting apprentices will be respirator and dust mask fit tested in their apprenticeship training program. Per OSHA Regulations (Title 8 CCR 5144(g)(1)(B)1, and Appendix A), an individual cannot wear a respirator, nor be fit tested, unless there is no hair touching the sealing surface of the respirator. Painting apprentices must be clean shaven during the time of the fit test at the ABC-GGC training program, and their contractor may require them to be clean shaven for their training assignment. The apprentice must bring their respirator, cartridges, and dust masks that they will utilize on the job site to class each day.
- Painting whites - required to wear while in the training facility. No soft material such as sweat pants, jogging pants, etc. are allowed in facility.
- Shirt with Sleeves – short sleeves shirts are acceptable, but cut off sleeves are not allowed
- Hard Hat – required at all times while working in the lab area
- Work Gloves – required when handling rough lumber, objects, or substances which might cut, tear, or burn your hands
- Respirator and Cartridges – fit tested
- Paint Brushes – Angle and Block
- Ear Protection
- Utility Knife
- 5-In-1 Painter’s Tool
- Putty Knife (optional – 5-In-1 Painter’s Tool may be used if preferred)
- Knee pads (option, but suggested)
- Masking Machine
- Rolling Poles and 9” Roller Frame
- Scientific Calculator (example: Texas Instruments; TI-30 – calculators on your phone are not allowed)
- Notepad, pen, pencil, and highlighter

Note:

Please mark and identify all tools and equipment (engrave or paint)

Students are required to bring these tools with them to class each day. There will be a tool check on the first day of class. Any student that is not prepared will be sent home. Any student that does not have their required tools at any time during the schooling period will be sent home due to being unprepared.